

HITACHI STOJANY

	<p>STOJAN L 170-72001</p> <p><u>Zastosowanie :</u> LR 170-411A</p>	<p>IA6103</p>
	<p>STOJAN</p> <p><u>Zastosowanie :</u> LR 170-419, - 422B</p>	<p>IA6104</p>
	<p>STOJAN L 190-2200, 23102-F6100</p> <p><u>Zastosowanie :</u> LR 190-704, -704B, -706, -707, -707B, -709, -711</p>	<p>IA6105</p>
	<p>STOJAN L170-12001, L180-1200 23102-07201 / -F2500 / -V7201</p> <p><u>Zastosowanie :</u> LR170-402E, -404B, -406C, -407T, -406B, -408T, -421T, -413, -414B, -417B, 412, LR180-01B</p>	<p>IA6110 / IA6140</p>
	<p>STOJAN L170-22002</p> <p><u>Zastosowanie :</u> LR170-420</p>	<p>IA6111</p>
	<p>STOJAN L170G-6200, -9200</p> <p><u>Zastosowanie :</u> LR170-505, -506, 704B, -745, -745B, -752, -752B</p>	<p>IA6112</p>







Nazwy i numery oryginalne użyte zostały wyłącznie jako propozycja zamienników

HITACHI STOJANY

	<p>STOJAN L170-22001, 23102-58500</p> <p><u>Zastosowanie :</u> LR170-714, -715B, -716B, -717, -719B</p>	<p>IA6113</p>
	<p>STOJAN L170-82001, 23102-0P00 /-0P600, L190G-2200, 23172-AA050</p> <p><u>Zastosowanie :</u> LR170-732C, LR190-715, -716, -717, -718, -719, -720</p>	<p>IA6132</p>
	<p>STOJAN L150-22004 /-82002, L160-52004, L140-42002, L170-4200</p> <p><u>Zastosowanie :</u> LR140-130P, -419T, -421T, -422T, LR150-98E, 99B, -218, -401C, -419B, -423B, -428</p>	<p>IA6138</p>
	<p>STOJAN L160-52002 / -72002 23102-29W00 /-05P01 L150-22001 / -22005</p> <p><u>Zastosowanie :</u> LR160-401</p>	<p>IA6139</p>
	<p>STOJAN L180-9200, 23102-64J00</p> <p><u>Zastosowanie :</u> LR180-725, -725C, -730, -731B, -731C, 733, 735, 738</p>	<p>IA6147</p>
	<p>STOJAN L150-52001 / -62002 L155-32001</p> <p><u>Zastosowanie :</u> LR155-16P, -408</p>	<p>IA6159</p>

Nazwy i numery oryginalne użyte zostały wyłącznie jako propozycja zamienników

HITACHI STOJANY

	<p>STOJAN L225-82001</p> <p><u>Zastosowanie :</u> LR225-67P, -408E, -409B, -412T, -414T, -415B, -418B</p>	<p>IA6160</p>
	<p>STOJAN L225-22001</p> <p><u>Zastosowanie :</u> LR225-65C, -65E, -68B, -80B</p>	<p>IA6180</p> <p><i>“Nowość”</i></p>
	<p>STOJAN L165-2200,</p> <p><u>Zastosowanie :</u> LR165-707B</p>	<p>IA6181</p> <p><i>“Nowość”</i></p>
	<p>STOJAN L160-32003</p> <p><u>Zastosowanie :</u> LR160-702B, -707, -708C</p>	<p>IA6182</p> <p><i>“Nowość”</i></p>
	<p>STOJAN L160-32001, -52001</p> <p><u>Zastosowanie :</u> LR160-92C, -96C, 107B, -108B, -131, -144, -164, -414, -417, -421C, -426T, -427T, -428, -436T</p>	<p>IA6183</p> <p><i>“Nowość”</i></p>
	<p>STOJAN L235-22001</p> <p><u>Zastosowanie :</u> LR235-70B, -75C, -78B, -402, -403T, -404T, -405T</p>	<p>IA6184</p> <p><i>“Nowość”</i></p>

Nazwy i numery oryginalne użyte zostały wyłącznie jako propozycja zamienników